

Alert number **[A12/00090/23](#)**

Notifying country	<b>Germany</b>
Product category	<b>Motor vehicles</b>
Type	<b>Consumer</b>
Product	<b>Passenger car</b>
Name	<b>Tourneo Connect</b>
Brand	<b>Ford</b>
EC-type approval/model	<b>SK e13*2018/858*00270*01</b>
Production dates	<b>3.03.2022 - 7.07.2022</b>
Company recall code	<b>22S70</b>
Product description	<b>Passenger car</b>
Risk type	<b>Injuries</b>
Risk description	<b>Lower control arms may not meet specifications, which can cause these parts to break. In such case a wheel might hit the wheel housing which in turn can lead to impaired steering and a loss of control of the vehicle, increasing the risk of an accident.</b>
Legal provisions (at EU level) and European standards against which the product was tested and did not comply	<b>The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.</b>
Country of origin	<b>Poland</b>
Measures taken by economic operators	<b>Recall of the product from end users Manufacturer</b>
Recall website	- <b><u><a href="https://www.fordtechservice.dealerconnection.com/">https://www.fordtechservice.dealerconnection.com/</a></u></b>
Products were found and measures were taken also in	<b>The Netherlands Poland Slovakia</b>