

Alert number **[A12/02575/24](#)**



Notifying country **Germany**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger van / Light commercial vehicle**

Name **Caddy Maxi**

Brand **VW**

EC-type approval/model **SKN
e13*2018/858*00003***

Production dates **13.05.2024 - 19.06.2024**

Company recall code **47U9**

Product description **Passenger van / Light commercial vehicle.**

Risk type **Injuries**

Risk description **Due to the incorrect screwing of the rear left brake line, a leak can occur where the brake hose is attached, leading to a slow loss of brake fluid. Braking performance can be affected, increasing the risk of accidents and injuries.**

Legal provisions (at EU level) and European standards against which the product was tested and did not comply **The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Country of origin **Poland**

Measures taken by economic operators

**Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in

Sweden